03500.017706.



PATENT PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:) Eveniment E Belumes
TOSHIKO MORII et al.	Examiner: F. Polyzos
Appl. No.: 10/705,860	: Group Art Unit: 2878
Filed: November 13, 2003	;)
For: IMAGE PICKUP APPARATUS, RADIATION IMAGE PICKUP APPARATUS AND RADIATION IMAGE PICKUP SYSTEM	·) :)
U.S. Patent No.: 6,989,540 B2	:
Issued: January 24, 2006) September 28, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

OCT 0 3 200c

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.000 to

0016.8556-1118398416654966 01-16-1811

0705A60 -100.00 OP

for such Certificate of Correction.

10/02/2006 SDENBOB1 00000053 6989540

01 FC:1811

103.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

John D. Magluyan/ Attorney for Patentees Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 119208v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,989,540 B2

DATED

January 24, 2006

INVENTOR(S) :

Morii et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 48, "detect" should read -- defect --.

COLUMN 3:

Line 25, "from" should be deleted.

COLUMN 9:

Line 6, "ohmic" should read -- first ohmic --.

COLUMN 12:

Line 20, "wiring. 201," should read -- wiring 201, --.

COLUMN 13:

Line 19, "layer" should read -- layer structure --.

COLUMN 15:

Line 3, "complicated therefore," should read -- complicated. Therefore, --.

COLUMN 16:

Line 55, "TFT, After" should read -- TFT. After --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 119206 (Form#30) PATENT NO. 6,989,540 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow

CERTIFICATE OF CORRECTION

PATENT NO.

6,989,540 B2

DATED

January 24, 2006

INVENTOR(S) :

Morii et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 44, "another," should read -- other, --.

COLUMN 19:

Line 63, "X-ray On" should read -- X-ray. On --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>6,989,540 B2</u>

No. of add'l. copies @ 30¢ per page

OCT - 3 2085 ⇒ ___

Form PTO 1050 (Rev. 3-82) 119206 (Form#30)

CERTIFICATE OF CORRECTION

PATENT NO.

6,989,540 B2

DATED

January 24, 2006

INVENTOR(S) :

Morii et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 48, "detect" should read -- defect --.

COLUMN 3:

Line 25, "from" should be deleted.

COLUMN 9:

Line 6, "ohmic" should read -- first ohmic --.

COLUMN 12:

Line 20, "wiring. 201," should read -- wiring 201, --.

COLUMN 13:

Line 19, "layer" should read -- layer structure --.

COLUMN 15:

Line 3, "complicated therefore," should read -- complicated. Therefore, --.

COLUMN 16:

Line 55, "TFT, After" should read -- TFT. After --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 6,989,540 B2

No. of add'l. copies @ 30¢ per page

DCT - 3 2005

Form PTO 1050 (Rev. 3-82) 119206 (Form#30)

CERTIFICATE OF CORRECTION

PATENT NO.

6,989,540 B2

DATED

January 24, 2006

INVENTOR(S) :

Morii et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 44, "another," should read -- other, --.

COLUMN 19:

Line 63, "X-ray On" should read -- X-ray. On --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 119206 (Form#30) PATENT NO. 6,989,540 B2

No. of add'l. copies @ 30¢ per page

CCI - 3 2000

